

**REQUEST FOR PROPOSAL
MIDWESTERN STATE UNIVERSITY
PURCHASING & CONTRACT MANAGEMENT DEPARTMENT
3410 Taft Blvd., Daniel Bldg., Rm. 202
Wichita Falls, TX. 76308**

BID NUMBER

735-16-8165

BID TITLE

**Exterior Window Painting Hardin
Building**

**BIDS WILL BE RECEIVED BY SEALED BID OR EMAIL UNTIL:
2:00 P.M.,
August 25, 2016 to:
the office's of the Director of Purchasing & Contract Management,
3410 Taft Blvd., Daniel Bldg., Rm. 202
Wichita Falls, TX. 76308**

GENERAL TERMS AND CONDITIONS

These General Terms and Conditions apply to all offers made to Midwestern State University (herein after referred to as "University") by all prospective vendors (herein after referred to as "Bidders") on behalf of Solicitations including, but not limited to, Invitations to Bid and Request for Quotes.

INSTRUCTIONS FOR SUBMITTING BIDS

Review this document in its entirety. Be sure your bid is complete, and double check your bid for accuracy.

Questions requiring only clarification of instructions or specifications will be handled through the email process. If any questions results in a change or addition to this Bid, the change(s) and addition(s) will be addressed to all vendors involved as quickly as possible in the form of an addendum. It is the responsibility of the bidder to view the posting on the MSU purchasing web page located at <http://mwsu.edu/purchasing/>.

Sign the **Vendor's Affidavit Notice** and return with your bid.

BIDDERS SHALL SUBMIT BID ON THE FORM PROVIDED, SIGN THE VENDOR AFFIDAVIT, AND RETURN ENTIRE BID PACKET. In the event of inclement weather and the University Offices are officially closed on a bid opening day, bids will be received until 2:00 p.m. of the next business day. At which time said bids will be privately opened.

BIDS SUBMITTED AFTER THE SUBMISSION DEADLINE SHALL BE RETURNED UNOPENED AND WILL BE CONSIDERED VOID AND UNACCEPTABLE.

SUCCESSFUL VENDOR WILL BE NOTIFIED BY EMAIL OR MAIL. All responding vendors will receive written notification regarding the outcome of the award. Bid tabulations will be posted to the MSU Purchasing we page.

PLEASE NOTE CAREFULLY

THIS IS THE ONLY APPROVED INSTRUCTION FOR THIS BID. ITEMS BELOW APPLY TO AND BECOME PART OF TERMS AND CONDITIONS OF BID. ANY EXCEPTIONS THERETO MUST BE IN WRITING.

1. Each bid shall be emailed or placed in a separate envelope completely and properly identified with the name and number of bid. Bids must be in the Purchasing Office **BEFORE** the hour and date specified.
2. **QUOTE F.O.B. DESTINATION.** If otherwise, show exact cost to deliver. Bid unit price on quantity specified – extend and show total. In case of errors in extension, UNIT prices shall govern. Bids subject to unlimited price increase will not be considered.
3. Bids **MUST** give full firm name and address of the bidder. Failure to manually sign bid will disqualify it. Person signing bid should show TITLE or AUTHORITY TO BIND HIS FIRM IN A CONTRACT.
4. Bids **CANNOT** be altered or amended after opening time. Any alterations made before opening time must be initialed by bidder or his authorized agent. No bid can be withdrawn after opening without the approval by the Vice-President of Administration & Finance based on a written acceptable reason.
5. The University is exempt from State Sales Tax and Federal Excise Tax. **DO NOT INCLUDE TAX IN BID.**
6. Any catalog, brand name or manufacturer's reference used in a bid invitation is descriptive-**NOT** restrictive-it is to indicate type and quality desired unless otherwise indicated. Bids on brand of like nature and quality will be considered. If bid is based on other than referenced specifications, proposal must show manufacturer, brand or trade name, lot number, etc., of article offered. If other than brand(s) specified is offered, illustrations and complete description should be made part of the bid. If bidder takes no exception to specifications or reference data, he will be required to furnish brand names, numbers, etc., as specified.

7. Samples, when requested, must be furnished free of expense to the University. If not destroyed in examination, they will be returned to the bidder on request, at his expense. Each sample should be marked with bidder's name, address, and University bid number. **DO NOT ENCLOSE OR ATTACH SAMPLE TO BID.**
8. **Delivery:** Bid must show number of days required to make delivery to place material in receiving agency's designated location under normal conditions. Failure to state delivery time obligates bidder to complete delivery in 14 calendar days. A five-day difference in delivery promise may break a tie. Unrealistically short or long delivery promises may cause bid to be disregarded. Consistent failure to meet delivery promises without valid reason may cause removal from bidder list. Delivery shall be made during normal working hours only, 8:00 a.m. to 5:00 p.m., unless prior approval for late delivery has been obtained from the Director of Purchasing.
9. If delay is foreseen, contractor shall give written notice to Director of Purchasing. The University has the right to extend delivery date if reasons appear valid. Contractor must keep University advised at all times of status of order. Default in promised delivery (without accepted reasons) or failure to meet specifications, authorizes the University to purchase supplies elsewhere and charge full increase in cost and handling to defaulting contractor.
10. All items proposed shall be new, in first class condition suitable for shipment and storage (Midwestern State University prefers recycled packaging whenever possible), unless otherwise indicated in bid. Verbal agreements to the University will not be recognized. All materials and services shall be subject to Purchaser's approval. Unsatisfactory materials will be returned at Seller's expense.
11. Written and verbal inquiries pertaining to bids must give Bid Number and Commodity.
12. No substitutions or cancellations permitted without written approval of Director of Purchasing.
13. The University reserves the right to accept or reject all or any part of any bid, waive minor technicalities and award to the Bidder that bids to the Best Value to the University. The University reserves the right to award by item or by total bid. Prices should be itemized.
14. Consistent and continued tie bidding could cause rejection of bids by the University and/or investigation for Anti-Trust violations.
15. The contractor agrees to protect the University from claims involving infringement of patents or copyrights.
16. This is a Quotation inquiry only and implies no obligation on the part of the University. All costs quotations must include all the various features needed to

satisfy the requirements. Note: No amounts will be paid for the items in this BID in excess of the amounts quoted.

17. **Award:** A written purchase order or notice of award mailed or otherwise furnished to the successful bidder within the time of acceptance specified in this package results in a binding contract without further action by either party.
18. **Variation in Quantity:** The University assumes no liability for commodities produced, processed or shipped in excess of the amount specified herein.
19. **Invoicing:** Bidder shall submit two (2) copies of an itemized invoice showing bid number and purchase order number to:

**Midwestern State University
Accounts Payable
3410 Taft Blvd.
Wichita Falls, TX. 76308**

20. **Payments:** The University, after receipt of completed order will make payment to the contractor within 30 days from the receipt of goods or invoice whichever is later. All partial shipment must be pre-approved by the Director of Purchasing. In the event of partial shipments the University is not required to make payments until the order is complete. Acceptance of and final payment for the item will be contingent upon satisfactory performance of the product received by the University.
21. **Discrimination:** In order to comply with the provisions of fair employment practices, the contractor agrees as follows; 1.) the contractor will not discriminate against any employee or applicant for employment because of race, sex, religion, handicap, or national origin; 2.) in all solicitations or advertisements for employees, the contractor will state that all qualified applicants will receive consideration without regard to race, color, sex, age, religion, handicap or national origin; 3.) the contractor will furnish such relevant information and reports as requested by the University for the purpose of determining compliance with these regulations; and 4.) failure of the contractor to comply with these laws will be deemed a breach of contract and it may be cancelled, terminated or suspended in whole or in part.
22. **Assignment:** Any contract entered into pursuant to this request is not assignable, nor the duties thereunder, by either party without the written consent of the other party in the contract.
23. **Other Remedies:** In addition to the remedies stated herein, the University has the right to pursue other remedies permitted by law or in equity.
24. **E-Verify:** Contractor is responsible to verify all employees are approved by The Homeland Security E-Verify program.

REQUEST FOR PROPOSAL

EXTERIOR WINDOW PAINTING HARDIN BUILDING MIDWESTERN STATE UNIVERSITY

It is the intent of these specifications to describe the minimum requirements for **the above titled project** at Midwestern State University in sufficient detail to secure comparable bids.

Each bidder must confirm he fully understands these specifications and the University's needs and satisfies himself that he is cognizant of all factors relating to requirements contained in these specifications.

The bid analysis will include compliance to bid specifications, past performance with vendor, references, delivery time, which will have a weighted average of 30 percent and the overall cost to the university, which will have a weighted average of 70 percent. Midwestern State University reserves the right to consider deviations from these specifications.

Award of this bid will be contingent on availability of Midwestern State University funds.

References shall be included on this bid form. Three current customers with a comparable purchase shall be listed with complete name, address, telephone number and contact person.

Bids must be submitted on this form and the bidder shall return the entire bid/specification package which will constitute a contract equally binding between the bidder and Midwestern State University if bids accepted by the University. Each bid shall be placed in a sealed envelope or emailed, signed by a person having the authority to bind his/her firm in a contract.

This contract shall remain in effect until completion and acceptance by the University. Midwestern State University reserves the right to enforce the performance of this contract in any manner prescribed by law or deemed to be in the best interest of the University in the event of breach or default if this contract. Midwestern State University reserves the right to terminate the contract immediately in the event the successful bidder fails to make delivery in accordance with the specifications.

Questions concerning these specifications should be directed via email no later than August 18, 2016 to:

Stephen Shelley, Director of Purchasing and Contract Management
3410 Taft Blvd. Daniel Bldg. Rm. 202
Wichita Falls, TX. 76308
stephen.shelley@mwsu.edu
(940) 397-4110

Midwestern State University may in its sole discretion respond in writing to questions concerning this bid request. Only MSU responses made by formal written addendum to this proposal shall be binding and shall be posted on the MSU purchasing web site located

at <http://mwsu.edu/purchasing/>. Oral or other written interpretations or clarifications shall be without legal effect.

All bids meeting the intent of this invitation to bid will be considered for award. Bidders taking exception to the specifications, or offering substitutions, shall state these exceptions by attachment as part of the bid. The absence of such a list shall indicate that the bidder has not taken exception and shall hold the bidder responsible to perform in strict accordance with the specifications of the invitation. Midwestern State University reserves the right to accept any and all or none of the exception(s) / substitution(s) deemed to be in the best interest of the University.

PRE-BID MEETING: A pre-bid meeting will be held at **10:00 a.m. on August 15, 2016** at the northwest corner of the Hardin building, exterior, Midwestern State University, 3410 Taft Blvd., Wichita Falls, Texas.

Proposals are to be sent via email or hand delivered to:

Stephen Shelley, Director of Purchasing and Contract Management
3410 Taft Blvd. Daniel Bldg. Rm. 202
Wichita Falls, TX. 76308
stephen.shelley@mwsu.edu
(940) 397-4110

SPECIFICATIONS

RFP #735-16-8165

Please see specifications and drawing at the below Link under current bid opportunities listed under the RFP number:

<http://mwsu.edu/purchasing/>

Please supply a HUB Subcontracting Plan with your bid, which can be found at the below listed link:

<http://www.window.state.tx.us/procurement/prog/hub/hub-subcontracting-plan/>

Please supply schedule and lead time for project with bid:

Supply an insurance certificate with your Bid.

Supply a W-9 With your Bid if new to Midwestern State University.

2005 Uniform General Conditions apply to this Bid and can be found at the below listed link:

<http://mwsu.edu/purchasing/contract-management>

A Bid Bond of 5% will be required with your Bid.

BID SHEET
EXTERIOR WINDOW PAINTING HARDIN BUILDING
RFP#735-16-8165

Base Bid:_____

Alternate #1:_____

Alternate #2:_____

Company Name:_____

Print Name:_____

Signature:_____

Email:_____

Telephone:_____

HARDIN EXTERIOR WINDOWS PAINTING

BACKGROUND:

The exterior windows of Midwestern State University's Hardin Administration Building are either wooden or metal framed with single pane glass. The condition of the existing paint has degraded substantially over recent years and was made worse on the western/southern windows in May 2013 as a result of a large hail storm (see photos at the end of this document for examples of the western windows' condition). Many of the windows have paint which is peeling and glazing which is loose or fallen off. Replacement of the glazing on wooden windows and priming/painting of all windows is the objective of this project.

SCOPE OF WORK:

The contractor shall complete the following tasks:

1. Scrape each window and frame to remove loose paint. Prime the wooden areas using Zinsser deep tint primer. Paint all wooden surfaces with a minimum of two top coats using Kelly-Moore AcryShield exterior low sheen paint (color is Hardin brown).
2. The attached sketches identify the location of each window needing to be painted or have its glazing replaced.
3. Due to the age of the building, the existing paint contains lead so proper precautions and removal/scraping procedures must be exercised at ALL times. Reference Texas Environmental Lead Reduction Rules (§295.201-220) for lead paint abatement removal procedures and requirements.
4. To assist bidders in understanding the condition of the existing windows, the windows were rated in the attached drawings on a scale from 1 to 10 with 1 requiring scraping/removal of virtually all paint to a 10 which should only require cleaning prior to painting (i.e., no scraping). Scraping, to some degree, is assumed to be necessary on any window rated less than a 10. The evaluation is subjective and was taken from the ground; bidders are ultimately responsible for assessing the exact needs of each window. See typical photos at the end of this scope of work for examples of window conditions.
5. There are 139 windows on the first floor and 161 on the second floor, NOT including the eight windows on the bell tower. All of these windows are to be repainted, including the eight bell tower windows. There are a few windows which have been replaced with aluminum windows; the contractor is not responsible for any work related to the aluminum windows. Window sizes vary, but are generally as follows: windows 1001-1019, 1047-1113, 1116-1139, and 2001-2012 are shown in Photo A (~55" x 32 1/2"); windows 2054-2092 and 2125-2162 are shown in Photo B (84" x 32"); windows 1020-1046, 1089-1113, 2017-2052, and 2093-2120 are shown in Photo C (95" x 43"); note, not all windows are shown in these photos, but this covers the vast majority. A lower percentage of the second floor windows include arches across the top. All windows have lattice work in their interior so there are multiple panes. All windows are metal frames except for the ones on the original/main building (windows 1020-1046, 1089-1113, 2015-2052, 2091-2124) which are wooden.
6. Many of the wooden (NOT metal) windows have glazing which is either very loose or it has fallen out. The contractor is responsible for the complete removal of all glazing from all wooden windows ONLY (windows 1020-1046, 1089-1113, 2015-2052, 2091-2124; i.e., all of the ones on the central/main Hardin building). MSU has previously replaced the glazing on windows 1020-1028 and 2015-2028 so the contractor shall not replace this glazing. Contractor shall remove the

glazing and replace it using DAP '33' Glazing. Follow manufacturer's recommendations for surface prep prior to installing new glazing. Replacement of glazing on metal windows is NOT part of this scope of work.

7. The existing glazing on the main/central building wooden windows tested positive for asbestos (see attached portion of the July 2000 report, pages 35, 36, 47, 60, 66-68). Proper abatement techniques/procedures shall be used by the contractor when removing/handling the glazing from windows 1029-1046 (1020-1028 already abated per item 6 above), 1089-1113, 2029-2052 (2015-2028 already abated per item 6 above), and 2091-2124. The windows for the northern section of Hardin and south Hardin do NOT contain ACM.
8. In instances where the caulk between the window frame and the building is cracked or missing, it shall be removed and replaced using a paintable siliconized acrylic caulk by Kelly-Moore or equivalent manufacturer.
9. Paint shall only appear on wooden surfaces and not on the glass or adjacent masonry. Contractor is responsible for removal of all paint/glazing from surfaces adjacent to the windows/frames.
10. Due to the height of the windows, a lift or scaffolding will be required to access them safely. Contractor shall take precautions to minimize damage to vegetation and repair any rutting caused by the use of lifts/heavy equipment.
11. The majority of the windows are on the second floor and shall be accessed via an articulating lift. Walking on the clay tile roof is not advised, but may be necessary for a few of them; contractor is responsible for replacing all damaged tiles as a result of any of their activity on the roof. There are eight windows on the bell tower (two on each of the four tower faces) which are ~4 stories high and over the center of the building. Access to these windows will require an articulating lift capable of reaching ~125'.
12. Replacement of wood components of windows due to rotting is not part of this contract. Such areas shall be identified to the Owner by the contractor PRIOR to any repainting activities.
13. There are ~12 air intake ducts on the top of Hardin, mostly on the western portion. Need to paint each of these intakes the same color as the windows. Some of the ducts are small wind turbines and some are as large as ~4'x4'x3'. Contractor shall not damage ANY roofing tile in the process of painting these ducts; contractor responsible for replacement of all damaged tiles resulting from the painting process. It is possible to paint these ducts by CAREFULLY standing on two tiles at a time.
14. There are many trees close to the building and the contractor should minimize removal of limbs to facilitate their work. Owner will not be responsible for tree limb removal unless the limbs are actually touching the window.

SCHEDULE:

Bidders shall submit a schedule for completion with their bid; work to begin no sooner than 9/1/16. On site work cannot occur due to events in and around Hardin on November 10-11. Additionally, MSU has a large Christmas display which covers almost the entire eastern lawn of Hardin beginning November 21 through January 1, 2017. While work can occur during this period it is highly recommended it be completed prior to November 21; work cannot occur on the east side of Hardin on 11/21. Placement of displays on the lawn begins in early October, but should not hamper painting activities or access to windows. Additionally, the southern portion of Hardin contains a testing center so painting/scraping on these windows will need to work around their testing schedule, particularly if Saturdays are selected as painting days.

ALTERNATES:

1. Provide pricing as Alternate #1 to reglaze, prime, and repaint per the notes above only the (wooden) windows in the original Hardin building which include windows 1020-1046, 1089-1113, 2015-2052, and 2091-2124. Windows for the north Hardin and south Hardin sections are not included in this alternate.
2. Provide pricing as Alternate #2 to paint only the western facing windows starting with 1001 through 1058 and 2001 through 2053. This price shall include reglazing, priming, and repainting the western wooden windows as noted in item 6 above as well as the other metal framed windows on the west side of the building.

Type A Windows, ~55" x 32 ½", from south Hardin, first floor



Type B Windows, ~72" x 20", from south Hardin, second floor



Type C Windows, ~95" x 43", west side of Hardin, first floor



Second floor windows, Hardin (some of the worst windows)



Close up of second floor windows, Hardin



Close up of second floor windows, Hardin



Close up of second floor windows, Hardin






Second floor windows, Hardin




Close up of second floor windows, Hardin









Red = subjective evaluation of window's condition.
 105 No scraping required.
 1 = complete scraping & glazing replacement required.
 -Any rating less than 9 requires some degree of scraping.





LOWER BELL TOWER

SCALE: N/A = 1'-0"



EESIS

110022 FM 3326 South - Hawley, Texas 79525
(915) 672-5719 - Fax (915) 695-8455 - (800) 793-7255 - email Thorncm@aol.com
In Conjunction with

NORTH AMERICAN ANALYTICAL LABS Inc.

4601 Buffalo Gap Road Suite A-5 - Abilene, TX 79606/ P.O. Box 6865/79608
(915) 691-0172 - (800) 234-3056 - email DEWalker555@aol.com

ASBESTOS BUILDING SURVEY

of

Hardin Administration

3410 Taft Boulevard
Wichita Falls, TX 76308

Building Number: 0001

Completed for

Midwestern State University

Report Date:

June 07, 2000

Report Number:

200035003

CONSULTANT:


Denny E. Walker

TDH License #10-5023

CONSULTANT:


Charles Thorn

TDH License #10-5047

INSPECTOR:


Steven E. Robb

TDH License #60-2004

INSPECTOR:


Tom Gill

TDH License #60-1835



TABLE OF CONTENTS

1.0 SUMMARY EVALUATION

- 1.1 PAST SITE HISTORY/CONSTRUCTION
- 1.2 ASBESTOS CONTAINING MATERIAL
 - 1.2.1 MISCELLANEOUS MATERIAL
 - 1.2.2 SURFACING MATERIAL
 - 1.2.3 THERMAL SYSTEM INSULATION
- 1.3 CONCLUSIONS AND RECOMMENDATIONS
- 1.4 LIMITATIONS AND REPRODUCTIONS
- 1.5 ACM HOMOGENEOUS AREA SUMMARY

2.0 HOMOGENEOUS AREA REPORT

- 2.0 THERMAL SYSTEM INSULATION
- 2.0 SURFACING MATERIAL
- 2.0 MISCELLANEOUS MATERIAL

3.0 LABORATORY ANALYSIS REPORTS

- 3.1 QUEST REPORT # 004603
- 3.2 QUEST REPORT # 004603B
- 3.3 CRISP REPORT # CAL0004946
- 3.4 CRISP REPORT # CAL0004946 AMENDED
- 3.5 CRISP REPORT # CAL00041024
- 3.6 CRISP REPORT # CAL00041077
- 3.7 CRISP REPORT # CAL00041085
- 3.8 CRISP REPORT # CAL00092650
- 3.9 CRISP REPORT # CAL00092769

4.0 LAB AND PERSONNEL CERTIFICATES

- 4.1 CONSULTANT AGENCY
- 4.2 ASBESTOS INDIVIDUAL CONSULTANT LICENSE
- 4.3 INDIVIDUAL INSPECTOR LICENSE
- 4.4 LABORATORY TDH - PLM - LICENSES &
NVLAP ACCREDITATION CERTIFICATE

5.0 APPENDICES:

- 5.1 APPENDIX A: RESPONSE ACTION TABLE
HAZARD RANK DECISION TREE
- 5.2 APPENDIX B: HOMOGENEOUS AREA CODES
- 5.3 INSPECTORS ASSURANCES
- 5.4 GUIDE TO READING REPORT
- 5.5 BUILDING DRAWINGS

SUMMARY EVALUATION

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003

Page: Page 1 of 45

Project Number: ACM-2000-01

Date: June 07, 2000

PAST SITE HISTORY/CONSTRUCTION

Records provided by MSU show this building to be 32,034 square feet in size. Original construction was completed in 1937. The building consists mainly of three floors and a basement. It also has carillons on a fourth level. The exterior of the building is typical construction of MSU properties, clay brick with herring bone accents. The roof has a slight pitch with clay over-lay shingles.

The interior finishes consists of painted and papered walls, carpeted and tiled floors, and drop ceiling tile grids. The tile grid does in some places, hide the original ceiling.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 2 of 45
Date: June 07, 2000

ASBESTOS CONTAINING MATERIAL SUMMARY

(The square and linear footages are approximations.)

This asbestos survey was conducted using the basic guidelines of the Asbestos Hazard Emergency Response Act (AHERA), except for the number of samples collected for each homogeneous area/material. The amount of samples were collected is consistent with the Texas Department of Health regulations. Samples were assigned a unique identifying number, placed in sealed containers and sent to the laboratory for analysis.

One hundred sixty-eight (168) samples were collected and analyzed in this survey. The samples were analyzed for asbestos content using polarized light microscopy (PLM) in accordance with the Environmental Protection Agency's "Interim method for the Determination of Asbestos in Bulk Insulation Samples" (EPA 600/M4-82-020, December, 1982).

The percentages of asbestos, where applicable, were determined by microscopic visual examination based on volume. Analyses were performed by Crisp Analytical Laboratories, LLC. And Quest MicroAnalytics, Inc. both of these labs are accredited by the National Voluntary Laboratory Accreditation Program (NVLAP). Both labs used are also licensed by the Texas Department of Health.

Asbestos containing building materials (ACBM) are assessed as being friable or non-friable. Friable materials can be pulverized into dust by hand pressure and have a higher potential for fiber release than non-friable ACM. Each type of material is also assigned a hazard rank based upon the level of damage currently apparent in the material and that, due to external factors, is likely to be damaged in the future. The hazard rank may range from 1, indicating little problem, to 7, which can indicate a serious health risk.

*

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 3 of 45
Date: June 07, 2000

Miscellaneous Material



Ceiling Tile	5	-	221	-	Friable	Hazard Rank: 2
Homog. Area Description:	12"x12" Ceiling tiles, white w/ random dot patterns.					
Amount of Material:	~13,300sf					
Homog. Area Definition:	This material can be found in the classrooms, hallways, and offices.					
Functional Space:	Public Area					
Sample Location:	Collected in main hall near the south stairs, at the center of the hall, At damage site.2-3-F.					
Primary Analysis Results:	<u>Amosite</u>				2%	
Secondary Analysis Results::	<u>No Asbestos Detect</u>				0%	
Tan fibrous ceiling tile.						

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003

Page: Page 4 of 45

Project Number: ACM-2000-01

Date: June 07, 2000

Miscellaneous Material

Ceiling Tile 5 - 222 - Friable Hazard Rank: 2

Homog. Area Description: 12"x12" Ceiling tiles, white w/ random dot patterns.

Amount of Material: ~13,300sf

Homog. Area Definition: This material can be found in the classrooms, hallways, and offices.

Functional Space: Public Area

Sample Location: Collected at north end of the main hall, at the center of damage site.2-3-F.

Primary Analysis Results: Amosite 0%

Secondary Analysis Results:: No Asbestos Detect 0%

Tan fibrous ceiling tile.


ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 5 of 45
Date: June 07, 2000

Miscellaneous Material



Floor Tile	13	-	202	-	Non-Friable	Hazard Rank: 1
Homog. Area Description:	12"X12" Floor tile brown w/ flecks.					
Amount of Material:	~22,900sf					
Homog. Area Definition:	This material can be found throughout the entire building.					
Functional Space:	Public Area					
Sample Location:	Collected from outside of room 229 at the corner, 2-3-F.					
Primary Analysis Results:	<u>Chrysotile</u> 2%					
Secondary Analysis Results::	0%					

Tan floor tile.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 6 of 45
Date: June 07, 2000

Miscellaneous Material

Floor Tile 13 - 203 - Non-Friable Hazard Rank: 1

Homog. Area Description: 12"X12" Floor tile brown w/ flecks.
Amount of Material: ~22,900sf
Homog. Area Definition: This material can be found throughout the entire building.
Functional Space: Public Area
Sample Location: Collected from room 212 at northwest corner behind the cove base, 2-3-F.
Primary Analysis Results: Chrysotile 2%
Secondary Analysis Results: Chrysotile 6%
Tan floor tile and black mastic.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 7 of 45
Date: June 07, 2000

Miscellaneous Material



Floor Tile	14	-	205	-	Non-Friable	Hazard Rank: 1
Homog. Area Description:	12"x12" Floor tile, white w/ flecks.					
Amount of Material:	~80sf					
Homog. Area Definition:	This material is in the vault room, or room 103-C.					
Functional Space:	Public Area					
Sample Location:	Collected from room 103-C, vault, 1-F.					
Primary Analysis Results:	<u>Chrysotile</u> 5%					
Secondary Analysis Results:	<u>No Asbestos Detect</u> 0%					
No asbestos detected in second layer mastic.						

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 8 of 45
Date: June 07, 2000

Miscellaneous Material

Floor Tile 14 - 206 - Non-Friable Hazard Rank: 1

Homog. Area Description: 12"x12" Floor tile, white w/ flecks.
Amount of Material: ~80sf
Homog. Area Definition: This material is in the vault room, or room 103-C.
Functional Space: Public Area
Sample Location: Collected from room 103-C, vault, 1-F.
Primary Analysis Results: Chrysotile 3%
Secondary Analysis Results: No Asbestos Detect 0%

No asbestos detected in second layer mastic.


ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 9 of 45
Date: June 07, 2000

Miscellaneous Material



Floor Tile	15	-	261	-	Non-Friable	Hazard Rank: 1
Homog. Area Description:	12"x12" floor tile, white w/ gray flecks.					
Amount of Material:	~120sf					
Homog. Area Definition:	Materials found in room 112- the file room, offices, & copy room.					
Functional Space:	Public Area					
Sample Location:	Collected from the copy room at wall 3.					
Primary Analysis Results:	<u>Chrysotile</u> 4%					
Secondary Analysis Results::	<u>No Asbestos Detect</u> 0%					
4% chrysotile was discovered in second layer mastic.						

ESEIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 10 of 45
Date: June 07, 2000

Miscellaneous Material

Floor Tile **15** - **259** - **Non-Friable** Hazard Rank: 1

Homog. Area Description: 12"x12" floor tile, white w/ gray flecks.
Amount of Material: ~120sf
Homog. Area Definition: Materials found in room 112- the file room, offices, & copy room.
Functional Space: Public Area
Sample Location: Collected from the file room at wall 3.
Primary Analysis Results: Chrysotile 7%
Secondary Analysis Results:: 0%

7% chrysotile was discovered in second layer mastic.

Floor Tile **15** - **260** - **Non-Friable** Hazard Rank: 1

Homog. Area Description: 12"x12" floor tile, white w/ gray flecks.
Amount of Material: ~120sf
Homog. Area Definition: Materials found in room 112- the file room, offices, & copy room.
Functional Space: Public Area
Sample Location: Collected from the file room at wall 3.
Primary Analysis Results: Chrysotile 3%
Secondary Analysis Results:: No Asbestos Detect 0%

3% chrysotile was discovered in second layer mastic.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 11 of 45
Date: June 07, 2000

Miscellaneous Material



Floor Tile	16	-	287	-	Friable	Hazard Rank: 4
Homog. Area Description:	9" x 9" floor tile, brown w/ black mastic.					
Amount of Material:	~540sf					
Homog. Area Definition:	Materials found in telephone equipment room.					
Functional Space:	Public Area					
Sample Location:	Collected from telephone room in the basement.					
Primary Analysis Results:	<u>Chrysotile</u> 8%					
Secondary Analysis Results::	<u>No Asbestos Detect</u> 0%					
Light brown floor tile.						

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003

Page: Page 12 of 45

Project Number: ACM-2000-01

Date: June 07, 2000

Miscellaneous Material

Floor Tile 16 - 288 - Friable Hazard Rank: 4

Homog. Area Description: 9" x 9" floor tile, brown w/ black mastic.

Amount of Material: ~540sf

Homog. Area Definition: Materials found in telephone equipment room.

Functional Space: Public Area

Sample Location: Collected from telephone room in the basement.

Primary Analysis Results: Chrysotile 5%

Secondary Analysis Results: No Asbestos Detect 0%

Light brown floor tile.


ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 13 of 45
Date: June 07, 2000

Miscellaneous Material



Floor Tile	17	-	308	-	Non-Friable	Hazard Rank: 3
Homog. Area Description:	Green floor tile					
Amount of Material:	~300sf					
Homog. Area Definition:	In the women's restroom , 1st floor					
Functional Space:	Public Area					
Sample Location:	Collected from women's bathroom on the first floor					
Primary Analysis Results:	<u>Chrysotile</u>		3%			
Secondary Analysis Results::	<u>Chrysotile</u>		2%			

Page: Page 14 of 45
Date: June 07, 2000

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 15 of 45
Date: June 07, 2000

Miscellaneous Material



Floor Tile	18	-	312	-	Non-Friable	Hazard Rank: 2
Homog. Area Description:	Floor tile					
Amount of Material:	~25sf					
Homog. Area Definition:	Salient area located in the women's bathroom on the first floor					
Functional Space:	Public Area					
Sample Location:	Collected from women's bathroom					
Primary Analysis Results:	<u>Chrysotile</u>		3%			
Secondary Analysis Results::	<u>Chrysotile</u>		5%			

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 16 of 45
Date: June 07, 2000

Miscellaneous Material

Floor Tile 18 - 313 - Non-Friable Hazard Rank: 2

Homog. Area Description: Floor tile
Amount of Material: ~25sf
Homog. Area Definition: Salient area located in the women's bathroom on the first floor
Functional Space: Public Area
Sample Location: Collected from women's bathroom
Primary Analysis Results: Chrysotile 2%
Secondary Analysis Results:: Chrysotile 4%

Floor Tile 18 - 314 - Non-Friable Hazard Rank: 2

Homog. Area Description: Floor tile
Amount of Material: ~25sf
Homog. Area Definition: Salient area located in the women's bathroom on the first floor
Functional Space: Public Area
Sample Location: Collected from women's bathroom
Primary Analysis Results: Chrysotile 3%
Secondary Analysis Results:: Chrysotile 2%

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 17 of 45
Date: June 07, 2000

Miscellaneous Material



Mastic	6	- 243 -	Non-Friable	Hazard Rank: 1
Homog. Area Description:	Black mastic under carpet.			
Amount of Material:	~474sf			
Homog. Area Definition:	Material was found under the carpet in all areas of the room 202 (Internal Auditor).			
Functional Space:	Public Area			
Sample Location:	Collected from room 202, copy room at the wall 2 behind door, 2-F.			
Primary Analysis Results:	<u>Chrysotile</u> 2%			
Secondary Analysis Results::	0%			
Yellow and black mastics.				

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 18 of 45
Date: June 07, 2000

Miscellaneous Material

Mastic	6	-	242	-	Non-Friable	Hazard Rank: 1
Homog. Area Description:	Black mastic under carpet.					
Amount of Material:	~474sf					
Homog. Area Definition:	Material was found under the carpet in all areas of the room 202 (Internal Auditor).					
Functional Space:	Public Area					
Sample Location:	Collected from room 202, copy room at the wall 2 behind door, 2-F.					
Primary Analysis Results:	<u>Chrysotile</u>					3%
Secondary Analysis Results::						0%

Yellow and black mastics.

Mastic	6	-	241	-	Non-Friable	Hazard Rank: 1
Homog. Area Description:	Black mastic under carpet.					
Amount of Material:	~474sf					
Homog. Area Definition:	Material was found under the carpet in all areas of the room 202 (Internal Auditor).					
Functional Space:	Public Area					
Sample Location:	Collected from room 202, copy room at the wall 2 behind door, 2-F.					
Primary Analysis Results:	<u>Chrysotile</u>					3%
Secondary Analysis Results::	<u>No Asbestos Detect</u>					0%

Yellow and black mastics.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 19 of 45
Date: June 07, 2000

Miscellaneous Material



Other 13 - 300 - **Friable** Hazard Rank: 1
Miscellaneous

Homog. Area Description: Gasket material at pipe connections.
Amount of Material: ~30 gaskets
Homog. Area Definition: Material found in mechanical room at pipe connection.
Functional Space: Mechanical
Sample Location: Collected from the mechanical room in the basement.
Primary Analysis Results: Chrysotile 55%
Secondary Analysis Results: 0%

Dark gray fibrous material with white fibers.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 20 of 45
Date: June 07, 2000

Miscellaneous Material

Other **13** - **298** - **Friable** Hazard Rank: 1
Miscellaneous

Homog. Area Description: Gasket material at pipe connections.
Amount of Material: ~30 gaskets
Homog. Area Definition: Material found in mechanical room at pipe connection.
Functional Space: Mechanical
Sample Location: Collected from the mechanical room in the basement.
Primary Analysis Results: Chrysotile 40%
Secondary Analysis Results: 0%

Black hard board.

EESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 21 of 45
Date: June 07, 2000

Miscellaneous Material



Roofing Material 1	- 171 -	Non-Friable Hazard Rank: 1
Homog. Area Description:	Black Tar and Mastic	
Amount of Material:	~100sf	
Homog. Area Definition:	This material is found in the bell tower.	
Functional Space:	Utility Area	
Sample Location:	Collected from the bell tower floor 2-3-F	
Primary Analysis Results:	<u>Chrysotile</u>	20%
Secondary Analysis Results::		0%
	Black Tar Mastic	

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 22 of 45
Date: June 07, 2000

Miscellaneous Material

Roofing Material 1 - 173 - Non-Friable Hazard Rank: 1

Homog. Area Description: Black Tar and Mastic
Amount of Material: ~100sf
Homog. Area Definition: This material is found in the bell tower.
Functional Space: Utility Area
Sample Location: Collected from the bell tower floor 2-3-F
Primary Analysis Results: Chrysotile 6%
Secondary Analysis Results: 0%

Black sealant and black tar on black canvas.

Roofing Material 1 - 172 - Non-Friable Hazard Rank: 1

Homog. Area Description: Black Tar and Mastic
Amount of Material: ~100sf
Homog. Area Definition: This material is found in the bell tower.
Functional Space: Utility Area
Sample Location: Collected from the bell tower floor 2-3-F
Primary Analysis Results: Chrysotile 5%
Secondary Analysis Results: 0%

Black sealant.


ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 23 of 45
Date: June 07, 2000

Miscellaneous Material



Sheet Rock	8	-	230	-	Friable	Hazard Rank: 1
Homog. Area Description:	Sheet rock w/ joint comp.					
Amount of Material:	~3,380sf					
Homog. Area Definition:	This material can be found on the 2nd floor, remodeled offices on the west side of the building.					
Functional Space:	Public Area					
Sample Location:	Collected from above the ceiling in the hall west at room 222, 2-3-F.					
Primary Analysis Results:	<u>Chrysotile</u> 2%					
Secondary Analysis Results::	0%					
Off-white joint compound.						

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 24 of 45
Date: June 07, 2000

Miscellaneous Material

Sheet Rock 8 - 231 - Friable Hazard Rank: 1

Homog. Area Description: Sheet rock w/ joint comp.
Amount of Material: ~3,380sf
Homog. Area Definition: This material can be found on the 2nd floor, remodeled offices on the west side of the building.
Functional Space: Public Area
Sample Location: Collected from the above ceiling form room 216, 2-3-F.
Primary Analysis Results: Chrysotile 2%
Secondary Analysis Results:: No Asbestos Detect 0%
White surfacing.

Sheet Rock 8 - 229 - Friable Hazard Rank: 1

Homog. Area Description: Sheet rock w/ joint comp.
Amount of Material: ~3,380sf
Homog. Area Definition: This material can be found on the 2nd floor, remodeled offices on the west side of the building.
Functional Space: Public Area
Sample Location: Collected from above the drop ceiling at the north entrance to the hallway for the new offices on the west side, 2-3-F.
Primary Analysis Results: Chrysotile 3% Primary Point Count Result 2.5%
Secondary Analysis Results:: No Asbestos Detect 0%
See amended report,004603,dated 4/7/00.

Sheet Rock 8 - 311 - Friable Hazard Rank: 1

Homog. Area Description: Sheet rock w/ joint comp.
Amount of Material: ~3,380sf
Homog. Area Definition: This material can be found on the 2nd floor, remodeled offices on the west side of the building.
Functional Space: Public Area
Sample Location: Collected from room #225, above door, above ceiling
Primary Analysis Results: Chrysotile 2%
Secondary Analysis Results:: 0%

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 25 of 45
Date: June 07, 2000

Miscellaneous Material



Sheet Rock	11	-	302	-	Friable	Hazard Rank: 1
Homog. Area Description:	Sheet rock with tape and joint compound.					
Amount of Material:	~1,088sf					
Homog. Area Definition:	Material found in telephone equipment room in the basement.					
Functional Space:	Public Area/Mechanical spaces					
Sample Location:	Collected from the center of wall three.					
Primary Analysis Results:	<u>Chrysotile</u> 2%					
Secondary Analysis Results::	<u>No Asbestos Detect</u> 0%					
Off-white joint compound.						

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003

Page: Page 26 of 45

Project Number: ACM-2000-01

Date: June 07, 2000

Miscellaneous Material

Sheet Rock 11 - 303 - Friable Hazard Rank: 1

Homog. Area Description: Sheet rock with tape and joint compound.

Amount of Material: ~1,088sf

Homog. Area Definition: Material found in telephone equipment room in the basement.

Functional Space: Public Area/Mechanical spaces

Sample Location: Collected from the south end of wall three.

Primary Analysis Results: Chrysotile 2%

Secondary Analysis Results:: 0%

White joint compound.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 27 of 45
Date: June 07, 2000

Miscellaneous Material



Transite	1	-	304	-	Non-Friable	Hazard Rank: 3
Homog. Area Description:	Transite board					
Amount of Material:	~180sf					
Homog. Area Definition:	Materials found in the windows					
Functional Space:	Public Area					
Sample Location:	Room #216, 2nd window from the left, above ceiling					
Primary Analysis Results:	<u>Chrysotile</u> 20%					
Secondary Analysis Results::	0%					

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 28 of 45
Date: June 07, 2000

Miscellaneous Material



Wall Tile	2	-	189	-	Friable	Hazard Rank: 2
Homog. Area Description:	12"x12"Sq. wall tile, white, with random dot & mastic.					
Amount of Material:	~1800sf					
Homog. Area Definition:	This material can be found in mechanical rooms, ceiling in entrance to stairs going to the 3rd floor, & classrooms.					
Functional Space:	Public Area					
Sample Location:	Collected from south mechanical room, 3rd floor, 2-3-F.					
Primary Analysis Results:	<u>Chrysotile</u> 4%					
Secondary Analysis Results::	<u>No Asbestos Detect</u> 0%					
4% chrysotile found in second layer mastic.						

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 29 of 45
Date: June 07, 2000

Miscellaneous Material

Wall Tile	2	-	190	-	Friable	Hazard Rank: 2
------------------	----------	----------	------------	----------	----------------	-----------------------

Homog. Area Description: 12"x12"Sq. wall tile, white, with random dot & mastic.
Amount of Material: ~1800sf
Homog. Area Definition: This material can be found in mechanical rooms, ceiling in entrance to stairs going to the 3rd floor, & classrooms.
Functional Space: Public Area
Sample Location: Collected from south mechanical room, 3rd floor, 2-3-F.
Primary Analysis Results: Chrysotile 2%
Secondary Analysis Results: No Asbestos Detect 0%
2% chrysotile found in second layer mastic.

Wall Tile	2	-	191	-	Friable	Hazard Rank: 2
------------------	----------	----------	------------	----------	----------------	-----------------------

Homog. Area Description: 12"x12"Sq. wall tile, white, with random dot & mastic.
Amount of Material: ~1800sf
Homog. Area Definition: This material can be found in mechanical rooms, ceiling in entrance to stairs going to the 3rd floor, & classrooms.
Functional Space: Public Area
Sample Location: Collected from north mechanical room, 3rd floor, 2-3-F.
Primary Analysis Results: Chrysotile 3%
Secondary Analysis Results: No Asbestos Detect 0%
3% chrysotile found in third layer mastic.


EESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 30 of 45
Date: June 07, 2000

Miscellaneous Material



Wall Tile	3	-	281	-	Friable	Hazard Rank: 4
Homog. Area Description:	18"x24" Sq. wall tile, white with random dot, with mastic					
Amount of Material:	~1440sf					
Homog. Area Definition:	Material found Basement of mechanical room the walls.					
Functional Space:	Mechanical					
Sample Location:	Collected from wall #1.					
Primary Analysis Results:	<u>Chrysotile</u> 3%					
Secondary Analysis Results::	0%					
3% Chrysotile was discovered in the second layer mastic.						

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 31 of 45
Date: June 07, 2000

Miscellaneous Material

Wall Tile 3 - 282 - Friable Hazard Rank: 4

Homog. Area Description: 18"x24" Sq. wall tile, white with random dot, with mastic

Amount of Material: ~1440sf

Homog. Area Definition: Material found Basement of mechanical room the walls.

Functional Space: Mechanical

Sample Location: Collected from wall #3.

Primary Analysis Results: **Chrysotile** 3%

Secondary Analysis Results:: 0%

3% Chrysotile was discovered in the second layer mastic.


ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 32 of 45
Date: June 07, 2000

Miscellaneous Material



Window Glazing 1	- 307 -	Friable	Hazard Rank: 2
Homog. Area Description:	Window Glaze		
Amount of Material:	~140 windows		
Homog. Area Definition:	On all windows		
Functional Space:	Public Area		
Sample Location:	Collected from window at room #108		
Primary Analysis Results:	<u>Chrysotile</u>	2%	
Secondary Analysis Results::		0%	

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.
SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 33 of 45
Date: June 07, 2000

Miscellaneous Material

Window Glazing 1	- 321 -	Friable	Hazard Rank: 2
Homog. Area Description:	Window Glaze		
Amount of Material:	~140 windows		
Homog. Area Definition:	On all windows		
Functional Space:	Public Area		
Sample Location:	Collected from room #107, at the restroom window		
Primary Analysis Results:	<u>Chrysotile</u>	2%	
Secondary Analysis Results::		0%	

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 34 of 45
Date: June 07, 2000

Surfacing Material



Texturizer	8	- 198 -	Non-Friable	Hazard Rank: 1
Homog. Area Description:	Yellow w/ waves and sheetrock.			
Amount of Material:	~660sf			
Homog. Area Definition:	The material can be found in room 208-C on the 2cd. Floor.			
Functional Space:	Public Area			
Sample Location:	Collected from room 208-C at wall 3 behind bookcase, 2-3-F.			
Primary Analysis Results:	<u>Chrysotile</u> 4%			
Secondary Analysis Results::	<u>No Asbestos Detect</u> 0%			
	White texture			

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 35 of 45
Date: June 07, 2000

Surfacing Material

Texturizer 8 - 199 - Non-Friable Hazard Rank: 1

Homog. Area Description: Yellow w/ waves and sheetrock.
Amount of Material: ~660sf
Homog. Area Definition: The material can be found in room 208-C on the 2cd. Floor.
Functional Space: Public Area
Sample Location: Collected from room 208-C form wall 2 behind cove base, 2-3-F.
Primary Analysis Results: Chrysotile 0%
Secondary Analysis Results:: No Asbestos Detect 0%

Tan surfacing

Texturizer 8 - 200 - Non-Friable Hazard Rank: 1

Homog. Area Description: Yellow w/ waves and sheetrock.
Amount of Material: ~660sf
Homog. Area Definition: The material can be found in room 208-C on the 2cd. Floor.
Functional Space: Public Area
Sample Location: Collected from room 208-C from wall 2 behind file cabinet, 2-3-F.
Primary Analysis Results: Chrysotile 2%
Secondary Analysis Results:: 0%

Tan surfacing and floor tile.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 36 of 45
Date: June 07, 2000

Thermal System Insulation



Elbow Wrap	4	-	273	-	Friable	Hazard Rank: 2
Homog. Area Description:	Pipe insulation elbows or fittings.					
Amount of Material:	~120elbows					
Homog. Area Definition:	This material is found in the mechanical rooms on the third floor, and the basement.					
Functional Space:	Mechanical					
Sample Location:	Collected from the basement mechanical room that is marked w/ red tape.					
Primary Analysis Results:	<u>Chrysotile</u> 2%					
Secondary Analysis Results::	<u>No Asbestos Detect</u> 0%					
Gray fibrous insulation.						

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003

Page: Page 37 of 45

Project Number: ACM-2000-01

Date: June 07, 2000

Thermal System Insulation

Elbow Wrap 4 - 272 - Friable Hazard Rank: 2

Homog. Area Description: Pipe insulation elbows or fittings.

Amount of Material: ~120elbows

Homog. Area Definition: This material is found in the mechanical rooms on the third floor, and the basement.

Functional Space: Mechanical

Sample Location: Collected from the basement mechanical room that is marked w/ red tape.

Primary Analysis Results: Chrysotile 4%

Secondary Analysis Results:: Chrysotile 0%

Gray fibrous insulation and white surfacing on canvas mesh.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 38 of 45
Date: June 07, 2000

Thermal System Insulation



HVAC Insulation 3 - 183 - **Non-Friable** Hazard Rank: 2

Homog. Area Description: White mastic on AC ducts.
Amount of Material: ~19060 lf
Homog. Area Definition: This material can be found in mechanical rooms and above drop ceilings throughout building.
Functional Space: Mechanical
Sample Location: Collected from south mechanical room, 2-3-F, 3rd. Floor.
Primary Analysis Results: Chrysotile 7%
Secondary Analysis Results: 0%
White mastic, silver foil, and yellow insulation.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 39 of 45
Date: June 07, 2000

Thermal System Insulation

HVAC Insulation 3 - 185 - Non-Friable Hazard Rank: 2

Homog. Area Description: White mastic on AC ducts.
Amount of Material: ~19060 lf
Homog. Area Definition: This material can be found in mechanical rooms and above drop ceilings throughout building.
Functional Space: Mechanical
Sample Location: Collected from north mechanical room, 2-3-F, 3rd. Floor.
Primary Analysis Results: Chrysotile 3%
Secondary Analysis Results:: 0%

Brown paper with white surfacing.


EESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 40 of 45
Date: June 07, 2000

Thermal System Insulation



Tank Insulation 1	- 297 -	Friable	Hazard Rank: 4
Homog. Area Description:	Tank insulation		
Amount of Material:	~80sf		
Homog. Area Definition:	In the basement mechanical room		
Functional Space:	Mechanical		
Sample Location:	Collected from west end of the tank.		
Primary Analysis Results:	<u>Chrysotile</u>	62%	
Secondary Analysis Results::	<u>Chrysotile</u>	0%	
	Gray fibrous insulation and pink surfacing on canvas.		

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.
SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 41 of 45
Date: June 07, 2000

Thermal System Insulation

Tank Insulation 1 - 296 - Friable Hazard Rank: 4

Homog. Area Description: Tank insulation
Amount of Material: ~80sf
Homog. Area Definition: In the basement mechanical room
Functional Space: Mechanical
Sample Location: Collected from center end of the tank.
Primary Analysis Results: Chrysotile 64%
Secondary Analysis Results:: Chrysotile 0%

Gray fibrous insulation and pink surfacing on canvas.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 42 of 45
Date: June 07, 2000

CONCLUSIONS AND RECOMMENDATIONS

CONCLUSION:

One hundred sixty-eight samples were taken of fifty-three homogenous materials or areas. Twenty three of those materials were found to contain over one percent of asbestos by one or both of the laboratories. The following materials contained greater than one percent asbestos. Individual sample values or composition can be found in the homogenous area report in section 2.0 of this report.

The black mastic referred to in this report as area MR-1. Three samples 171, 172, and 173 were taken and all were identified positive. This material can be found on the bell tower floor. There is approximately 100 square feet of this material.

The white mastic referred to in this report as area AC-3. Three samples 183, 184, and 185 were taken and two, (183, 185), were identified positive. This material can be found in the mechanical rooms on the third floor and the HVAC ducts throughout the building. There is approximately 19,060 linear feet of this material.

The 12" white wall tile referred to in this report as area MWT-2. Three samples 189, 190, and 191 were taken and all were identified positive for having second layer mastic, ACM. This material can be found in the mechanical rooms, third floor staircase and classrooms. There is approximately 1800 square feet of this material.

The yellow wall texturizer referred to in this report as area SMT-8. Three samples 198, 199, and 200 were taken and two, (198, 200), were identified positive. This material can be found in room 208. There is approximately 660 square feet of this material.

The 12" brown floor tile referred to in this report as area MFT-13. Three samples 201, 202, and 203 were taken and two, (202, 203), were identified positive. This material can be found throughout the entire building. There is approximately 22,900 square feet of this material.

The 12" White floor tile referred to in this report as area MFT-14. Three samples 204, 205, and 206 were taken and two, (205, 206), were identified positive. This material can be found in the vault in room 103. There is approximately 80 square feet of this material.

The 12" white ceiling tile referred to in this report as area MCT-5. Three samples 220, 221, and 222 were taken and one, (221), identified positive. This material can be found throughout the building. There is approximately 13,300 square feet of this material.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003

Page: Page 43 of 45

Project Number: ACM-2000-01

Date: June 07, 2000

The sheet rock referred to in this report as area MSR-8. Three samples 229, 230, and 231 were taken and all identified positive. This material can be found in the remodeled office area on the second floors west side. There is approximately 3,380 square feet of this material.

The black mastic referred to in this report as area MM-6. Three samples 241, 242, and 243 were taken and all identified positive. This material can be found under the carpet in room 202. There is approximately 474 square feet of this material.

The 12" white/gray floor tile referred to in this report as area MFT-15. Three samples 259, 260, and 261 were taken and all identified positive for having second layer mastic, ACM. This material can be found in file and copy room of 112. There is approximately 120 square feet of this material.

The elbow insulation referred to in this report as area EW-4. Three samples 271, 272, and 273 were taken and two, (272, 273), were identified positive. This material can be found in the mechanical rooms. There is approximately 120 elbows.

The 18" x 24" white wall tile referred to in this report as area MWT-3. Three samples 280, 281, and 282 were taken and two, (281, 282), were identified positive for having second layer mastic, ACM. This material can be found in the basement mechanical room. There is approximately 1440 square feet of this material.

The 9" brown floor tile referred to in this report as area MFT-16. Three samples 286, 287, and 288 were taken and two, (287, 288), were identified positive. This material can be found in the basement telephone room. There is approximately 540 square feet of this material.

The tank insulation referred to in this report as area TI-1. Three samples 295, 296, and 297 were taken and two, (296, 297), were identified positive. This material can be found on the heat exchangers in the basement mechanical rooms. There is approximately 80 square feet of this material.

The gasket material referred to in this report as area MO-13. Three samples 298, 299, and 300 were taken and two, (298, 299), were identified positive. This material can be found at the pipe connections in the mechanical rooms. There is approximately 30 gaskets.

The sheet rock referred to in this report as area MSR-11. Three samples 301, 302, and 303 were taken and two, (302, 303) were identified. This material can be found in the basement telephone room. There is approximately 1088 square feet of this material.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 44 of 45
Date: June 07, 2000

The transite board referred to in this report as area MTRB-1. One sample, 304 was taken and identified positive. This material can found throughout the windows. There is approximately 180 square feet of this material.

The window glaze referred to in this report as area MWG-1. Four samples 305, 306, 307, and 321 were taken and two, (304, 321), came back positive. This material can be found on all windows. There is approximately 140 windows.

The 9" green floor tile referred to in this report as area MFT-17. Three samples 308, 309, and 310 were taken and all were identified positive in all layers. This material can be found in the women's first floor bathroom lobby. There is approximately 300 square feet of this material.

The sheet rock referred to in this report as area MSR-12. One sample, 311 was taken and identified positive. This material is to be included in area MSR-8.

The 9" tan floor tile referred to in this report as area MFT-18. Three samples 312, 313, and 314 were taken and all identified positive in all layers. This material appears to be a salient repair to area MFT-17. There is approximately 25 square feet of this material.

The paneling mastic referred to in this report as area MO-14. Five samples, 322, 323, 324, 325, and 326 were taken and four, (322, 323, 324, 325), identified positive. This material can be found behind the light and dark paneling in several offices on the first and second floors. There is approximately 6,500 square feet of this material.

The tile grout referred to in this report as area MG-2. Three samples, 330, 331, and 332 were taken and all identified positive. This material can be found on the wall of the presidents restroom. There is approximately 80 square feet of this material.

The tile grout referred to in this report as area MG-3. Three samples, 333, 334, and 335 were taken and two, (333, 334) identified positive. This material can be found on the floor of the presidents restroom. There is approximately 60 square feet of this material.

There are six fire doors on the second floor of Hardin Main. These doors are assumed to contain asbestos. Any physical inspection to verify the presence of asbestos would compromise the integrity of these doors.

RECOMMENDATION:

Remove exposed mastic where wall tiles have fallen or are missing in mechanical rooms and do not replace.

Remove exposed and broken tile from telephone room and encapsulate exposed floor until

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

SUMMARY EVALUATION

Report Number: 200035003
Project Number: ACM-2000-01

Page: Page 45 of 45
Date: June 07, 2000

such a time that complete removal/renovation is possible.

In mechanical rooms damage thermal insulations on pipes and other components should be repaired or replaced as soon as possible.

After the above referenced repair the materials should all be incorporated into an Operations and Maintenance Program and managed in place until such time as the materials will be disturbed in a renovation or they become damaged to the point of needing localized repairs.

Should any of the above identified ACM need to be disturbed or removed, the following regulations should be adhered to. State of Texas, Federal, and OSHA regulations require that all asbestos containing building materials (ACBM) in public buildings in Texas that will be disturbed in any demolition or renovation activities must be removed by Texas Department of Health licensed and certified personnel (i.e.. Asbestos Consultant, Asbestos Abatement Contractor, Asbestos Abatement Workers, and Air Monitoring Technicians) prior to the demolition or renovation activities by general construction personnel.

LIMITATIONS AND REPRODUCTIONS

Neither ESESIS, nor NAAL Inc. makes any warranty, assurance, or guarantee that other asbestos containing materials may not be in the building in hidden or inaccessible areas.

This report has been prepared on behalf of and for the exclusive use of Midwestern State University for use in an environmental evaluation of this building. This report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party, nor used by any other party in whole or in part, without the written consent of ESESIS, or NAAL Inc.

ACM Homogeneous Area Summary

Page 1 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Ceiling Tile	5	~13,300sf		
<i>Sample Number</i> 221			Amosite	2%
			No Asbestos Detected	0%
Comments: Tan fibrous ceiling tile.				
<i>Sample Number</i> 222			Amosite	0%
			No Asbestos Detected	0%
Comments: Tan fibrous ceiling tile.				
Elbow Wrap	4	~120elbows		
<i>Sample Number</i> 272			Chrysotile	4%
			Chrysotile	0%
Comments: Gray fibrous insulation and white surfacing on canvas mesh.				
<i>Sample Number</i> 273			Chrysotile	2%
			No Asbestos Detected	0%
Comments: Gray fibrous insulation.				
Floor Tile	13	~22,900sf		
<i>Sample Number</i> 202			Chrysotile	2%
				0%
Comments: Tan floor tile.				
<i>Sample Number</i> 203			Chrysotile	2%
			Chrysotile	6%
Comments: Tan floor tile and black mastic.				

ACM Homogeneous Area Summary

Page 2 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Floor Tile	14	~80sf		
<i>Sample Number</i> 205			Chrysotile	5%
			No Asbestos Detected	0%
Comments: No asbestos detected in second layer mastic.				
<i>Sample Number</i> 206			Chrysotile	3%
			No Asbestos Detected	0%
Comments: No asbestos detected in second layer mastic.				
Floor Tile	15	~120sf		
<i>Sample Number</i> 259			Chrysotile	7%
				0%
Comments: 7% chrysotile was discovered in second layer mastic.				
<i>Sample Number</i> 260			Chrysotile	3%
			No Asbestos Detected	0%
Comments: 3% chrysotile was discovered in second layer mastic.				
<i>Sample Number</i> 261			Chrysotile	4%
			No Asbestos Detected	0%
Comments: 4% chrysotile was discovered in second layer mastic.				

ACM Homogeneous Area Summary

Page 3 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Floor Tile	16	~540sf		
<i>Sample Number</i> 287			Chrysotile	8%
			No Asbestos Detected	0%
Comments: Light brown floor tile.				
<i>Sample Number</i> 288			Chrysotile	5%
			No Asbestos Detected	0%
Comments: Light brown floor tile.				
Floor Tile	17	~300sf		
<i>Sample Number</i> 308			Chrysotile	3%
			Chrysotile	2%
Comments:				
<i>Sample Number</i> 309			Chrysotile	3%
			Chrysotile	4%
Comments:				
<i>Sample Number</i> 310			Chrysotile	2%
			Chrysotile	4%
Comments:				

ACM Homogeneous Area Summary

Page 4 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Floor Tile	18	~25sf		
<i>Sample Number</i>	312		Chrysotile	3%
			Chrysotile	5%
Comments:				
<i>Sample Number</i>	313		Chrysotile	2%
			Chrysotile	4%
Comments:				
<i>Sample Number</i>	314		Chrysotile	3%
			Chrysotile	2%
Comments:				
Grout	2	~80 square feet		
<i>Sample Number</i>	330		Chrysotile	2%
				0%
Comments:				
<i>Sample Number</i>	331		Chrysotile	2%
				0%
Comments:				
<i>Sample Number</i>	332		Chrysotile	2%
				0%
Comments:				

ACM Homogeneous Area Summary

Page 5 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Grout	3	~60 Square feet		
<i>Sample Number</i>	333		Chrysotile	2%
				0%
Comments:				
<i>Sample Number</i>	334		Chrysotile	2%
				0%
Comments:				
<i>Sample Number</i>	335		Chrysotile	0%
				0%
Comments:				
HVAC Insulation	3	~19060 lf		
<i>Sample Number</i>	183		Chrysotile	7%
				0%
Comments: White mastic, silver foil, and yellow insulation.				
<i>Sample Number</i>	185		Chrysotile	3%
				0%
Comments: Brown paper with white surfacing.				

ACM Homogeneous Area Summary

Page 6 of 12

Report Number: 200035003

Homogeneous Area	Amount of Material	Type and Percent of Asbestos Detected	
Mastic	6	~474sf	
<i>Sample Number</i> 241		Chrysotile	3%
		No Asbestos Detected	0%
Comments: Yellow and black mastics.			
<i>Sample Number</i> 242		Chrysotile	3%
			0%
Comments: Yellow and black mastics.			
<i>Sample Number</i> 243		Chrysotile	2%
			0%
Comments: Yellow and black mastics.			
Other Miscellaneous	8		
<i>Sample Number</i> 193		Chrysotile	0%
			0%
Comments: Thick brown rubber tile.			
<i>Sample Number</i> 194		Chrysotile	0%
			0%
Comments: Thick brown rubber tile.			

ACM Homogeneous Area Summary

Page 7 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Other Miscellaneous	13	~30 gaskets		
<i>Sample Number</i>	298		Chrysotile	40% 0%
Comments: Black hard board.				
<i>Sample Number</i>	300		Chrysotile	55% 0%
Comments: Dark gray fibrous material with white fibers.				
Other Miscellaneous	14	~6,500 Square feet		
<i>Sample Number</i>	322		Chrysotile	5% 0%
Comments:				
<i>Sample Number</i>	323		Chrysotile	5% 0%
Comments:				
<i>Sample Number</i>	324		Chrysotile	5% 0%
Comments:				
<i>Sample Number</i>	325		Chrysotile	0% 0%
Comments: Less than 1% found				
<i>Sample Number</i>	326		Chrysotile	4% 0%
Comments:				

ACM Homogeneous Area Summary

Page 8 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Roofing Material	1	~100sf		
<i>Sample Number</i>	171		Chrysotile	20%
				0%
Comments: Black Tar Mastic				
<i>Sample Number</i>	172		Chrysotile	5%
				0%
Comments: Black sealant.				
<i>Sample Number</i>	173		Chrysotile	6%
				0%
Comments: Black sealant and black tar on black canvas.				
Sheet Rock	8	~3,380sf		
<i>Sample Number</i>	229		Chrysotile	3%
			No Asbestos Detected	0%
Comments: See amended report,004603,dated 4/7/00.				
<i>Sample Number</i>	230		Chrysotile	2%
				0%
Comments: Off-whit joint compound.				
<i>Sample Number</i>	231		Chrysotile	2%
			No Asbestos Detected	0%
Comments: White surfacing.				
<i>Sample Number</i>	311		Chrysotile	2%
				0%
Comments:				

ACM Homogeneous Area Summary

Page 9 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Sheet Rock	11	~1,088sf		
<i>Sample Number</i> 302			Chrysotile	2%
			No Asbestos Detected	0%
Comments: Off-white joint compound.				
<i>Sample Number</i> 303			Chrysotile	2%
				0%
Comments: White joint compound.				
Tank Insulation	1	~80sf		
<i>Sample Number</i> 296			Chrysotile	64%
			Chrysotile	0%
Comments: Gray fibrous insulation and pink surfacing on canvas.				
<i>Sample Number</i> 297			Chrysotile	62%
			Chrysotile	0%
Comments: Gray fibrous insulation and pink surfacing on canvas.				
Texturizer	7			
<i>Sample Number</i> 196			Chrysotile	0%
			No Asbestos Detected	0%
Comments: Off-white textured surfacing.				
<i>Sample Number</i> 197			Chrysotile	0%
				0%
Comments: Yellow and white textured surfacing.				

ACM Homogeneous Area Summary

Page 10 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Texturizer	8	~660sf		
<i>Sample Number</i> 198			Chrysotile	4%
			No Asbestos Detected	0%
Comments: White texture				
<i>Sample Number</i> 199			Chrysotile	0%
			No Asbestos Detected	0%
Comments: Tan surfacing				
<i>Sample Number</i> 200			Chrysotile	2%
				0%
Comments: Tan surfacing and floor tile.				
Transite	1	~180sf		
<i>Sample Number</i> 304			Chrysotile	20%
				0%
Comments:				

ACM Homogeneous Area Summary

Page 11 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Wall Tile	2	~1800sf		
<i>Sample Number</i> 189			Chrysotile	4%
			No Asbestos Detected	0%
Comments: 4% chrysotile found in second layer mastic.				
<i>Sample Number</i> 190			Chrysotile	2%
			No Asbestos Detected	0%
Comments: 2% chrysotile found in second layer mastic.				
<i>Sample Number</i> 191			Chrysotile	3%
			No Asbestos Detected	0%
Comments: 3% chrysotile found in third layer mastic.				
Wall Tile	3	~1440sf		
<i>Sample Number</i> 281			Chrysotile	3%
				0%
Comments: 3% Chrysotile was discovered in the second layer mastic.				
<i>Sample Number</i> 282			Chrysotile	3%
				0%
Comments: 3% Chrysotile was discovered in the second layer mastic.				

ACM Homogeneous Area Summary

Page 12 of 12

Report Number: 200035003

Homogeneous Area		Amount of Material	Type and Percent of Asbestos Detected	
Window Glazing	1	~140 windows		
<i>Sample Number</i> 307			Chrysotile	2%
				0%
Comments:				
<i>Sample Number</i> 321			Chrysotile	2%
				0%
Comments:				


APPENDICES

RESPONSE ACTIONS BASED ON HAZARD RANKING

HAZARD RANK	REMOVAL PRIORITY	AHERA CATEGORIES	RESPONSE ACTIONS REQUIRED BY AHERA
7	1	Significantly Damaged	Evacuate or isolate the area if needed. Remove the ACBM (or enclose or encapsulate if sufficient to contain fibers). Repair of thermal system insulation is allowed if feasible and safe. Operations and maintenance plan required for all friable asbestos containing building materials.
6	2	Damaged plus potential for significant damage	Evacuate or isolate the area if needed. Remove, enclose, encapsulate, or repair to correct damage. Take steps to reduce potential for disturbance. Operations and maintenance plan required for all friable asbestos containing building materials..
5	3	Damaged plus potential for damage	Remove, enclose, encapsulate, or repair to correct damage. Take steps to reduce potential for disturbance. Operations and maintenance plan required for all friable asbestos containing building materials.
4	4	Damaged	Same as Hazard Rank 5
3	5	Potential for significant damage	Evacuate or isolate the area if needed. Take steps to reduce potential for disturbance. Operations and maintenance plan required for all friable asbestos containing building materials.
2	6	Potential for damage	Operations and maintenance plan required for all friable asbestos containing building materials.
1	7	No problem	Operations and maintenance plan required for all friable asbestos containing building materials, but measures need not be as extensive as above.

NOTE: AHERA does not account for combinations of current and potential damage (i.e. hazard ranks #5 and 6). The response actions shown are combinations of those required for each condition.

CLASSIFICATIONS FOR HAZARD POTENTIAL (DECISION TREE DISPLAY)



HOMOGENEOUS AREA CODES

<u>MATERIAL CATEGORY</u>	<u>MATERIAL TYPE</u>	<u>CODE</u>
Miscellaneous Material	Building Insulation	MBI
Miscellaneous Material	Carpet Mastic	MCPT
Miscellaneous Material	Caulk	MC
Miscellaneous Material	Ceiling Tile	MCT
Miscellaneous Material	Cloth/Rope	MCTH
Miscellaneous Material	Counter/Furniture Surfaces	MCS
Miscellaneous Material	Curtains (fire)	MCU
Miscellaneous Material	Door Insulation	MDI
Miscellaneous Material	Electrical Insulation	MEI
Miscellaneous Material	Flex Connector	MFC
Miscellaneous Material	Floor Tile	MFT
Miscellaneous Material	Grout	MG
Miscellaneous Material	Linoleum	MLN
Miscellaneous Material	Mastic	MM
Miscellaneous Material	Other Miscellaneous	MO
Miscellaneous Material	Roofing Material	MR
Miscellaneous Material	Sheet Rock	MSR
Miscellaneous Material	Substrate	MSS
Miscellaneous Material	Tape	MTP
Miscellaneous Material	Transite	MTRB
Miscellaneous Material	Wall Tile	MWT
Miscellaneous Material	Wallboard	MWB
Miscellaneous Material	Window Glazing	MWG
Surfacing Material	Exterior Coat	SMXC
Surfacing Material	Fireproofing	SMF
Surfacing Material	Other Surfacing	SO
Surfacing Material	Paint	SMP
Surfacing Material	Spray-on Material	SMSM
Surfacing Material	Tape Compound	SMTC
Surfacing Material	Texturizer	SMT
Surfacing Material	Topcoat	SMCT
Thermal System Insulation	Elbow Wrap	EW
Thermal System Insulation	Freezer Insulation	FI
Thermal System Insulation	HVAC Insulation	AC
Thermal System Insulation	Other TSI	TO
Thermal System Insulation	Pipe "T"	TW
Thermal System Insulation	Pipe Insulation	PR
Thermal System Insulation	Tank Insulation	TI

INSPECTOR'S ASSURANCES

The person who conducted this inspection has successfully completed an EPA approved training course on the inspection of buildings for asbestos containing materials. Current state and federal regulations regarding such inspections were followed by the inspector, as applicable to this particular inspection.


Name of Inspector (Printed): **Charles Thorn**

Inspector's Signature:



Name of Inspector (Printed): **Tom Gill**

Inspector's Signature:




Name of Inspector (Printed): **Steven E. Robb**

Inspector's Signature:



Name of Inspector (Printed): **Denny E. Walker**

Inspector's Signature:



Certificate/License number: See Personnel and Laboratory Licenses section of this report.

Date of Certification: See Personnel and Laboratory Licenses section of this report.

ESESIS and NORTH AMERICAN ANALYTICAL LABS Inc.

Guide to Reading Report

Report Number: 200035003

Project Number: ACM-2000-01

This instruction page is included with each report to explain the structure of the report and to enable clients to interpret our sample numbering system. If you have any questions after reading this report or if anything in it is not clear to you please do not hesitate to call us.

Following this instruction page you will find a written summary which describes and interprets the detailed information found in the rest of the report. It begins with a brief description of the building's construction and a history of any major structural changes in the site (PAST SITE HISTORY / CONSTRUCTION) . This is followed by the ASBESTOS CONTAINING MATERIAL SUMMARY section which describes the methods used to inspect the building and analyze samples. This section also contains a detailed description of the nature of any asbestos containing materials (ACM) including their appearance, location, the approximate quantity present, and a hazard rank ranging from 1 (no immediate danger) to 7 (substantial health risk). The next section, CONCLUSIONS AND RECOMMENDATIONS, gives you our professional opinion as to which areas of the building represent the greatest problem and ways in which these problems may be addressed. The final section of the summary, LIMITATIONS AND REPRODUCTIONS, is designed to inform you of the scope of the inspection and any qualifications which should be used in interpreting its results.

The HOMOGENEOUS AREA REPORT provides a detailed description of each sample of material collected during the inspection. The BULK SAMPLE REPORT includes a cover letter, detailed results for each sample analyzed, and a summary which shows which samples contained asbestos and which did not. APPENDICES which follow the report include a description of ESESIS' homogeneous area codes and a detailed explanation of hazard ranks.

The following is an explanation of the numbering system ESESIS uses to label each sample listed in the summary and homogeneous area reports. Each begins with the unique control number assigned by the laboratory to each sample analyzed. Next the code describing the type of homogeneous area from which the sample was taken is given (codes are explained on the homogeneous area code list included in the appendices). This code may be preceded by an "SA" which indicates that this is a salient (isolated) homogeneous area. The code is also followed by a number used to distinguish the area from others of the same type. Next comes the field sample number assigned to the sample by the inspector when it was collected. The entire number is concluded with the project number or designation, if any, which distinguishes this inspection from any others that may be conducted for the same client.

Once again, if you have any trouble interpreting the information you find in this report please do not hesitate to call us. We at ESESIS appreciate your business.



RAULPH D. PERKINS 60071
 EXPIRES: 31 JULY 2001
 DATE BORN:



HARPER PERONE ARCHITECTS, INC.
4724 OLD JACOBSON HIGHWAY
MONTA FALLO, TEXAS 75555-3505
FAX: 956/397-5471

3410 TAFT BLVD.

WICHITA FALLS, TEXAS

(915) 695-8455 fax

HAWLEY, TX 79525

HAWLEY, TX 79525

(915) 695-8455 fax


00251

© 2000 McGraw-Hill Companies, Inc.

HARDIN BLDG.


101 - MAIN

SCALE: 1/16" = 1'-0"



4. CEILING TILE = MCT 12. GROUT = MG
11. FLOOR TILE = MFT 19. TRANSITE = MTRB
38. OTHER MISCELLANEOUS MATERIAL = MO

- INDICATES A SAMPLE THAT HAS REVEALED AN
ASBESTOS CONTAINING SUBSTANCE
- REFER TO EESIS REPORT FOR VERIFICATION OF ALL
LOCATIONS OF SAMPLES AND ASBESTOS CONTAINING
SUBSTANCES.






PAULINE P. HANSEN
REGISTERED ARCHITECT
DATE BOARDED
12/20/2010
HARDIN PERMANENT ARCHITECTS, INC.
1720 SOUTH ALLEN ROAD, SUITE 100
WICHITA FALLS, TEXAS 76798-1000
TEL: 817-265-1111 FAX: 817-265-1112



HARDIN ADMINISTRATION MIDWESTERN STATE UNIVERSITY

3410 TAFT BLVD WICHITA FALLS, TEXAS


ESESIS
11022 FM 3326 SOUTH
HAWLEY, TX 79525
(915)793-7255 tel.
(915)695-8455 fax



DRAWN BY: W. Powers	
DATE: 3-15-2020	
REVISIONS	
NO.	DESCRIPTION


00251

HARDIN BLDG.
201 - MAIN



HARDIN ADMINISTRATION BUILDING - MAIN - SECOND FLOOR

SCALE: 1/16" = 1'-0"



SCALE: 1/16" = 1'-0"

VENDOR REFERENCES

Please list three (3) references of current customers who can verify the quality of service your company provides. The University prefers customers of similar size and scope of work to this proposal. ***THIS FORM MUST BE RETURNED WITH YOUR PROPOSAL.***

REFERENCE ONE

Government/CompanyName: _____

Address: _____

ContactPersonandTitle: _____

Phone: _____ Fax: _____

Contract Period: _____ ScopeofWork: _____

REFERENCE TWO

Government/CompanyName: _____

Address: _____

ContactPersonandTitle: _____

Phone: _____ Fax: _____

Contract Period: _____ ScopeofWork: _____

REFERENCE THREE

Government/CompanyName: _____

Address: _____

ContactPersonandTitle: _____

Phone: _____ Fax: _____

Contract Period: _____ ScopeofWork: _____

AFFIDAVIT

The undersigned certifies that the bid prices contained in this proposal have been carefully checked and are submitted as correct and final and if bid is accepted (within 90 days unless otherwise noted by vendor), agrees to furnish any and/or all items upon which prices are offered, at the price(s) and upon the conditions contained in the Specifications.

STATE OF TEXAS
COUNTY OF WICHITA

BEFORE ME, the undersigned authority, a Notary Public in and for the State of Texas, on this day personally appeared

who, after having first been duly sworn, upon oath did depose and say;

That the foregoing proposal submitted by _____

____ hereinafter called "Bidder" is the duly authorized agent of said company and that the person signing said proposal has been duly authorized to execute the same. Bidder affirms that they are duly authorized to execute this contract, that this company, corporation, firm, partnership or individual has not prepared this bid in collusion with any other Bidder, and that the contents of this bid as to prices, terms or conditions of said bid have not been communicated by the undersigned nor by any employee or agent to any other person engaged in this type of business prior to the official opening of this bid.

Name and Address of Bidder:

Telephone number _____

Email _____

Signature

Name: _____

Title: _____

SWORN TO AND SUBSCRIBED BEFORE ME THIS _____ day of _____,
20 _____.

Notary Public in and for the
State of Texas.

**AGREEMENT BETWEEN
MIDWESTERN STATE UNIVERSITY
AND**

CONTRACT NO.

This Agreement made the _____ day of _____ in the year 20____, by and between _____, hereinafter called the Contractor, and the Board of Regents of Midwestern State University, hereinafter called the Owner,

WITNESSETH, that the Contractor and the Owner for the consideration hereinafter named agree as follows:

ARTICLE 1. SCOPE OF WORK: The Contractor shall furnish all of the materials and perform all of the work shown on the drawings and described in the specifications for the project entitled _____. These drawings and specifications prepared for Midwestern State University by _____, acting as and in these Contract Documents entitled the Project Architect. The Contractor shall do everything required by this Agreement, the General and Supplemental Conditions of the Contract, the Special Conditions, the Addenda, the Specifications, the Drawings, the Historically Underutilized Business (HUB) Subcontracting Plan, and the Proposal attached as **Exhibit 1** (including any unit prices stated therein).

The Specifications and Drawings are enumerated as follows:

SPECIFICATIONS: See attached as **Exhibit 2**.

DRAWINGS: See attached as **Exhibit 2**.

ADDENDA: See attached as **Exhibit 2**.

ALTERNATES: The following Alternate Proposals, fully described in the Specifications, are included as a part of this Contract: _____.

ARTICLE 2. TIME OF COMPLETION: The Owner shall provide a Notice to Proceed in which a date for commencement of the work shall be stated; such commencement date shall be 10 or more days after the date of the notice. The Contractor shall achieve substantial completion of the work within _____ (_____) calendar days after such commencement date, as such completion date may be extended by approved Change Orders. The time set forth for completion of the work is an essential element of the Contract.

ARTICLE 3. THE CONTRACT SUM: The Owner shall pay the Contractor for performance of the Contract, subject to additions and deductions provided therein, the sum of (\$ _____), and make payment on account as hereinafter provided.

ARTICLE 4. HUB SUBCONTRACTING PLAN: The Owner has adopted Exhibit H, Policy on Utilization of Historically Underutilized Business ("Policy"), which is incorporated herein by reference. Contractor, as a provision of the Agreement must comply with the requirements of the Policy and adhere to the HUB Subcontracting Plan submitted with Contractor's Proposal and attached as **Exhibit 3**. No changes to the HUB Subcontracting Plan can be made by the Contractor without the prior written approval of the Owner in accordance with the Policy.

ARTICLE 5. LIQUIDATED DAMAGES: For each consecutive calendar day after the substantial completion period set forth in Article 2 above that any work, including the correction of deficiencies found during the final testing and inspection, is not completed, the amount of (\$) will be deducted from the money due or becomes due the Contractor, not as a penalty but as liquidated damages representing the parties' estimate at the time of contract execution of the damages which the Owner will sustain for late completion.

ARTICLE 6. CERTIFICATION OF NO ASBESTOS CONTAINING MATERIALS OR WORK:

The Contractor shall provide a certification statement, included with each materials submittal, stating that no asbestos containing materials or work is included within the scope of the proposed submittal.

The Contractor shall insure that Texas Department of Health licensed individuals, consultants or companies are used for any required asbestos work including asbestos inspection, asbestos abatement plans/specifications, asbestos abatement, asbestos project management and third-party asbestos monitoring.

The Contractor shall provide at Substantial Completion, a notarized affidavit to the Owner and the Architect stating that no asbestos containing materials or work was provided, installed, furnished or added to the Project.

The Contractor shall take whatever measures he deems necessary to insure that all employees, suppliers, fabricators, materialmen, subcontractors, or their assigns, comply with this requirement.

All materials used on this Project shall be certified as non Asbestos Containing Building Materials (ACBM). The Contractor shall insure compliance with the following acts from all of his subcontractors and assigns:

Asbestos Hazard Emergency Response Act (AHERA—40 CFR 763-99 (7));

National Emission Standards for Hazardous Air Pollutants (NESHAP—EPA 40 CFR 61, National Emission Standard for Asbestos;

Texas Asbestos Health Protection Rules (TAHRP—Tex. Admin. Code Title 25, Part 1, Ch. 295C, Asbestos Health Protection

Every subcontractor shall provide a notarized statement that no ACBM has been used, provided, or left on this Project.

The Contractor shall provide, in hard copy and electronic form, all necessary material safety data sheets (MSDS) of all products used in the construction of the Project to the Texas Department of Health licensed inspector or Project Architect or Engineer who will compile the information from the MSDS and, finding no asbestos in any of the product, make a certification statement.

At Final Completion the Contractor shall provide a notarized certification statement per TAC Title 25 Part 1, Ch. 295.34, par. c.1 that no ACBM was used during construction of the Project.

ARTICLE 7. ACCEPTANCE OF BID OR AWARD OF CONTRACT: By signing this Agreement, the undersigned certifies as follows:

Assignment. This Agreement is a personal service contract for the services of Construction, and Contractor's interest in this Agreement, duties hereunder and/or fees due hereunder may not be assigned or delegated to a third party.

Records of expenses pertaining to Additional Services and services performed on the basis of a Worker Wage Rate or Monthly Salary Rate shall be kept on the basis of generally accepted accounting principles and in accordance with cost accounting standards promulgated by the Federal Office of Management and Budget Cost Accounting Standards Board and shall be available for audit by the Owner or the Owner's authorized representative on reasonable notice.

Family Code Child Support Certification. Pursuant to Section 231.006, Texas Family Code, Service Provider certifies that it is not ineligible to receive the award of or payments under this Agreement and acknowledges that this Agreement may be terminated and payment may be withheld if this certification is inaccurate.

Eligibility Certification. Pursuant to Section 2155.004, Texas Government Code, Service Provider certifies that the individual or business entity named in this Agreement is not ineligible to receive the award of or payments under this Agreement and acknowledges that this Agreement may be terminated and payment withheld if this certification is inaccurate.

Franchise Tax Certification. A corporate or limited liability company Contractor certifies that it is not currently delinquent in the payment of any Franchise Taxes due under Chapter 171 of the Texas Tax Code, or that the corporation or limited liability company is exempt from the payment of such taxes, or that the corporation or limited liability company is an out-of-state corporation or limited liability company that is not subject to the Texas Franchise Tax, whichever is applicable.

Payment of Debt or Delinquency to the State. Pursuant to Sections 2107.008 and 2252.903, Texas Government Code, Contractor agrees that any payments owing to Contractor under this Agreement may be applied directly toward any debt or delinquency that Contractor owes the State of Texas or any agency of the State of Texas regardless of when it arises, until such debt or delinquency is paid in full.

Entire Agreement; Modifications. This Agreement supersedes all prior agreements, written or oral, between Contractor and Owner and shall constitute the entire Agreement and understanding between the parties with respect to the Project. This Agreement and each of its provisions shall be binding upon the parties and may not be waived, modified, amended or altered except by a writing signed by Contractor and Owner.

Captions. The captions of paragraphs in this Agreement are for convenience only and shall not be considered or referred to in resolving questions of interpretation or construction.

Governing Law and Venue. This Agreement and all of the rights and obligations of the parties and all of the terms and conditions shall be construed, interpreted and applied in accordance with and governed by and enforced under the laws of the State of Texas without reference to its conflicts of law provisions. The county where the Project is located shall be the sole place of venue for any legal action arising from or related to this Agreement or the Project in which the Owner is a party.

Waivers. No delay or omission by either party in exercising any right or power arising from non compliance or failure of performance by the other party with any of the provisions of this Agreement shall impair or constitute a waiver of any such right or power. A waiver by either party of any covenant or condition of this Agreement shall not be construed as a waiver of any subsequent breach of that or of any other covenant or condition of the Agreement.

Binding Effect. This Agreement shall be binding upon and inure to the benefit of the parties and their respective permitted assigns and successors.

Appointment. Owner hereby expressly reserves the right from time to time to designate by notice to Contractor a representative(s) to act partially or wholly for Owner in connection with the performance of Owner's obligations. Contractor shall act only upon instructions from the designated representative(s) unless otherwise specifically notified to the contrary.

Records. Records of Contractor's costs, reimbursable expenses pertaining to the Project and payments shall be available to Owner or its authorized representative during business hours and shall be retained for four (4) years after final Payment or abandonment of the Project, unless Owner otherwise instructs Contractor in writing.

Notices. All notices, consents, approvals, demands, requests or other communications relied on by the parties shall be in writing. Written notice shall be deemed to have been given when delivered in person to the designated representative of the Contractor or Owner for whom it is intended; or sent by U. S. Mail to the last known business address of the designated representative; or transmitted by fax machine to the last known business fax number of the designated representative.

Mail notices are deemed effective upon receipt or on the third business day after the date of mailing, whichever is sooner. Fax notices are deemed effective the next business day after faxing.

Severability. Should any term or provision of this Agreement be held invalid or unenforceable in any respect, the remaining terms and provisions shall not be affected and this Agreement shall be construed as if the invalid or unenforceable term or provision had never been included.

Illegal Dumping. The Contractor shall ensure that it and all of its Subcontractors and assigns prevent illegal dumping of litter in accordance with Title 5, Texas Health and Safety Code, Chapter 365.

Ethics Matters/No Financial Interest. Contractor and its employees, agents, representatives and subcontractors have read and understand University's Conflicts of Interest Policy, University's Standards of Conduct Guide and applicable state ethics laws and rules. Neither Contractor nor its employees, agents, representatives or subcontractors will assist or cause University employees to violate University's Conflicts of Interest Policy, provisions described by University's Standards of Conduct Guide, or applicable state ethics laws or rules. Contractor represents and warrants that no member of the Board has a direct or indirect financial interest in the transaction that is the subject of this Agreement.

By signature hereon, Contractor certifies that no member of the Board of Regents of Midwestern State University, or Executive Officers, including component institutions, has a financial interest, directly or indirectly, in the transaction that is the subject of this contract.

BY SIGNING BELOW, the Parties have executed and bound themselves to this Agreement as of the day and year first above written.

MIDWESTERN STATE UNIVERSITY

By: _____
Signature

Print name

Date: _____

By: _____
Signature

Print name

Date: _____

SAMPLE