



Office of Purchasing/Contract Management
3410 Taft Boulevard Wichita Falls, Texas 76308-2099

ADDENDUM ONE

August 18, 2016

TO WHOM IT MAY CONCERN


Reference: RFP #735-16-8165 Exterior Window Painting Hardin Building

Per pre-bid meeting held August 15, ,2016 produced the following information which becomes part of the bid documents. Please add the following to the scope of the project:

1. Contractor is responsible for repairs to the soil, sidewalks, irrigation system, or shrubbery caused by their construction activities. Ruts caused by a lift shall be filled in by the contractor at their expense. MSU will identify the sprinkler heads prior to the contractor working in an area, as long as the contractor provides at least two business days' notice.
2. Roofing tile was repaired recently so all tile are considered in good condition unless the contractor shows broken ones to MSU prior to starting ANY work in an area. Broken tiles seen after the contractor has been working in an area will be considered the contractor's responsibility to replace.
3. There are no known broken windows in Hardin. As with the roofing tile, the contractor shall identify broken glass prior to beginning work in an area. If work has begun in an area and glass has been identified as being broken, the contractor will be responsible for its replacement.

If you have any questions please contact me.

Thank You.

Sincerely,

Stephen Shelley

Director of Purchasing/Contract Management

stephen.shelley@mwsu.edu

940 397-4110

mwsu.edu

An Equal Opportunity/Affirmative Action Employer and Educator