

July 24, 2024

ADDENDUM THREE (3)

RE: RFP 735-2023-4388 Redwine Chiller Replacement Project

TO WHOM IT MAY CONCERN,

Please see the response to the question submitted below:

- 1. What size conduit and wire is existing? Contractor should confirm the existing conditions in the field.
- Is the existing wire and breaker the correct size and amperage for new equipment? It is the
 correct size for the existing equipment. If a vendor's equipment requires different wire size and
 breaker, it is the vendor's responsibility to replace these existing components and any other
 items necessary to meet code.
- 3. Will there need to be any new circuits ran for new equipment? Not by the Owner. If a vendor's equipment requires new circuits, the vendor is responsible for installing them

Please remember to acknowledge this addendum on the Addenda Checklist.

The deadline for submitting responses has passed. No additional questions will receive a response. Regards,

Joseph J. Mrugalski

Purchasing/Contract Management