

Rusty conduit to be replaced from light to j-box shown in photo. See additional length in IMG_9486 photo.

